

---

# Jose Villalobos, P.E.

President

JLV Wolf Inc.

---

## **Education**

MS, Civil Engineering, Stanford University

BS, Civil Engineering, California State University, Los Angeles

## **Registration and Certification**

Civil Engineer, CA (C26659)

Corrosion Engineer, CA (CR1006)

Civil Engineer, NV (015884)

PE, TX (79525)

PE,KS (PE27301)

PE, OR (91708PE)

## **Founded JLV Wolf Inc. 2022**

## **Founded V&A 1979**

## **Total Years of Experience 42**

## **Professional Training**

First Aid/CPR

Confined Space Entry

Asbestos Awareness

## **Associations**

American Water Works Association

NACE International

Water Environment Federation

American Public Works Association

American Society of Civil Engineers

## **Technical Publications**

*Causes and Control of Deterioration, Standard Handbook of Plant Engineering, McGraw Hill, 1994*

*Concrete Surface Preparation 101 for Existing Concrete Manholes, CoatingsPro, 2007, p. 18*

*Protecting Underground Assets with Close-Interval Surveys, UIM,2007*

*Corrosion and Corrosion Control for Wastewater Treatment Plants, Volume 13B Corrosion, ASM International, 2005*

*Recirculation Hot Water Can Corrode Pipes, Consulting Specifying Engineer, 2007, p. 46*

## **Experience Summary**

Mr. Villalobos is a licensed civil and corrosion engineer with over 48 years of experience in the design and condition assessment of corrosion protection systems for municipal infrastructure including water and wastewater conveyance, treatment, and storage.

## **Relevant Project Experience**

A.C. Transit, Oakland, Bus Maintenance Facility Buries Hydraulic Fluid Line Investigation

Thompson vs. Standard Oil

Landels Ripley Diamond Union Oil Tank Investigation

Field, Richardson et al – Contra Costa Water District PG&E Claims Seaport Center Stainless Steel Pipe Support Cable Failure and Corrosion of Concrete Piles

Bay View Condominiums Copper Recirculation Hot Water Systems San Luis Water District Cement Mortar Coated Pipe Failure

Sea Colony Residential Housing Subdivision Reinforced Concrete Slab Foundation Failure

Pacifica Pier, Corrosion Investigation

Blue Water Litigation in East Bay MUD Service Area  
As-Needed Technical Services for the Resort at Squaw Creek

Bremer et al Cox & Sons Plumbing Sun City Copper Pipe Case

Bremer et al Cox & Sons Weber v. Del Webb Copper Pipe

Greenbriar Homes Valley Apts. Water Piping Evaluation Plan

Las Gallinas Valley SD Coll Sys H2S Expert Witness Study

Daley & Heft – W. Tolbert v. El Cajon, et al Case GIE028951

Bremer et al Pioneer Tapatio I HOA v Wigwam Copper Pipe

KB Homes v. California Rockridge

Celanese v. KBR CWA

Greenbriar Homes Veranda Copper Piping

Kennedy Souza El Cortez Hotel Copper Pipe Leak Eval Collins Plumbing 134699

King County Cawelo v. Ameron Case File No. 16290

Butz City of San Diego Landslide ACP Condition Assessment

Hot Water recirculation Case Washington State for Commercial Bldg.

Corrosion of Steel Water Tank at Water Treatment Plant Missouri